Tuesday, 12/18/2007 10:54:57 AM Date: Kim Johnston User **Process Sheet** : GASKET **Drawing Name** Customer : CU-DAR001 Dart Helicopters Services Job Number : 36419 Estimate Number : 12903 NA **Part Number** : D355811 P.O. Number S.O. No. : NA : D3558 REV B : 12/18/2007 **Drawing Number** This Issue : N/A : NC Prsht Rev. Project Number : 12/18/2007 : SMALL /MED FAB First Issue Type **Drawing Revision** : 33014 : NA Material Previous Run : 1/20/2008 Qty: 10 Um: Each Due Date Written By Checked & Approved By New Issue 07.06.12 EC Comment : Est Rev:A Est Rev:B Rev B dwg 07-12-06 DD Additional Product Job Number: Machine Or Operation: Description: Seq. #: MNEO60S063 NEOPRENE SHEET 0.063 1.0 Comment: Qty.: 0.6867 sf(s)/Unit Total: 6.8670 sf(s) **NEOPRENE SHEET 0.063** B07-17-20 106614 Batch: FLOW WATER JET 2.0 WATER JET Comment: FLOW WATER JET 1-Cut as per Dwg D3558 Dwg Rev: 1307-12-20 Prog Rev:\_ 2-Deburr if necessary 3.0 QC2 INSPECT PARTS AS THEY COME OFF MACHINE TURIV 1307-12-20 Comment: INSPECT PARTS AS THEY COME OFF MACHINE 4.0 QC8 SECOND CHECK Comment: SECOND CHECK PACKAGING PACKAGING RESOURCE #1 5.0 Comment: PACKAGING RESOURCE #1 Identify and Stock Location:

Page 1

Form: rorocess

## Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
07.12.70	3.0	TYPO HOLE PITCH DOSSELL SHOW						
		, <b>u</b>						

Part No: _	PAR #: _	Fault Category:	NCR: Yes No	DQA:	Date:	01/10/0
			QA: N/C C	losed:	Date:	

NCR:		W	ORK OR	DER NON-CONFORMANC	E (NCR)		:	
		Description of NC		Corrective Action Section B			A L	AI
DATE	STEP	Section A	Initial Action Description Sign & Chief Eng Chief Eng Date		Verification Section C	Approval Chief Eng	Approval QC Inspector	
07.13.30	3.0	P.C. Humman 2000	045 045 047 047	DRAWING SHOULD READ S.65'.' AS PITCH HLLEPTARLE DEVIATION.	p# per USI U41 07.12.20		_	Stelan
								104
							i	
							1	
							ı	

NOTE: Date & initial all entries

Date:

Tuesday, 12/18/2007 10:54:57 AM

User:

Kim Johnston

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: GASKET

Job Number: 36419

Part Number: D355811

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE


Job Completion



U A-1224

Dart Ae	rospace	e Ltd						
W/O:			W	ORK ORDER CHANGES	<b>,</b>			
DATE	STEP	PROCEDURE CHANGE			Ву	Date Q	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	:							
		·						
Part No	•	PAR #:	Fault Cat	egory:	ICR: Yes	No DQA: _	Date: _	
					QA: N	I/C Closed: _	Date: _	
NCR:			WORK OR	DER NON-CONFORMAN	CE (NCF	₹)	;	
		Description of NC		Corrective Action Section B	Section B Verifica		n Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section C	Chief Eng	QC Inspector
	-							
		•						
	1						,	

NOTE: Date & initial all entries



و (الله						
DART AERO	SPACE LTD				Work Order:	36419
Description:	GASKET				Part Number:	D3558-II
Inspection Dwg	g: <u>D3558</u> -   Rev:	B.				Page 1 of 1
	FIRST	ARTICLE IN		ON CHE		
Drawin <b>g</b> Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø .19	+,005-001	, 19	×	·		
,30	7030	,30	بلا			
,30	4030	.30	×			
2,06	4- ,030	2.07	*		,	
2.73	4030	2,73	A			
,38	t/. 030	138	*			
22.50	1/030	22.50	<b>*</b>			
26.50	t030	O2. H	ף			
			,			
			,			
						•
					•	
				-		
		-				

Measured by: B	Audited by:		Prototype Approval:	v	<i></i>
Date: 07 - 12-30	Date: 1	-112/21	Date:		4
Barrier 18		·			

Rev Da	te Change	Revised I	by Approved
A	New Issue	KJ/JLM	ay Approved

	Transport gage tras or 10 m	
w.		
•		